








# Eliminator Torsion Axles

with Quick Change Spindles


The Eliminator Torsion Axle has an industry first with its removable spindle. Gone are the days of sitting by the side of the road when the spindle is damaged due to extreme bearing failure or due to an accident.



No Load



Normal Load



Heavy Shock

Tools required to change spindle:

- 1-1/2" Wrench
- Pliers
- Heavy Hammer
- Lug Wrench
- Jack & Jack Stand

TIE DOWN ENGINEERING • 5901 Wheaton Drive • Atlanta GA, 30336  
www.tiedown.com • (404) 344-0000 • Fax (404) 349-0401

